

Stainless Steel Electrodes (MMAW)

SME 308-16



 **SENOR[®]**
One Stop Solution for Welding & Brazing Consumables

SME 308-16

Stick Electrodes (MMAW)

Stainless Steel

Classifications:

AWS A/SFA 5.4 : E 308-16
 IS 5206 : E 19.9 R26
 Coating Type : Rutile
 Coating Factor : Medium
 Identification : Brand Printed

Characteristics:

SME 308-16 is a Stainless Steel electrode with controlled Ferrite content of 3 to 7% for maximum resistance to cracking, corrosion and high temperatures up to 800°C. It is suitable for welding performance in all positions and has high resistance to cracking. It gives arc stability and low spatter loss. All sizes strike and re-strike easily. The slag is easily controlled and does not interfere with the arc action. Weld beads are smooth, and of good appearance.



Applications:

- 1) Welding of 18Cr/8Ni grade Stainless Steels such as AISI types 301, 302, 304 and 308
- 2) Dairy, distillery and restaurant equipment, Petrochemical and chemical tanks
- 3) Steels of difficult weld ability, for building-up stainless surfaces on centrifugal pump impellers and shafts, valve faces, seats.

Mechanical Properties – All-Weld:

Condition	UTS MPa	% Elong (L=4Xd)	RA %	Ferrite No.
As Welded	560-660	35-50	50 min.	3-7

Weld Metal Chemistry (wt%):

C	Mn	Si	S	P	Ni	Cr
0.08 max	0.70-2.0	0.30-0.85	0.03 max	0.04 max	9.0-11.0	18.0-21.0

Current Conditions: AC, DC (+):

5.0	4.0	3.2	2.5	2.0	1.6
150-180	110-140	80-100	50-75	35-45	25-35

Welding Positions:

F, H, V-up, OH

Re-drying Conditions:

To obtain best results re dry the electrodes at 300°C for 1hour (Optionally available in vacuum-packed condition, re-drying not required in this packaging).

Note On Usage:

- 1) Keep electrode dry (Optionally also available in vacuum-packed condition, redrying not required in this packaging)
- 2) To obtain best results rebake the electrodes at 250 ~ 300°C for 1 hour and keep it at 100 ~ 150°C prior to use.
- 3) Use stainless steel wire brush for cleaning of slags
- 4) Follow the recommended welding parameters to achieve good sound welds
- 5) Do not use excessive currents. Hold short arc. Use good fit-up on joints.

Above are basic guidelines and will vary depending on joint design, number of passes and other factors.

⚠WARNING Ⓢ

Protect yourself and others. Read and understand this warning. Do not remove this warning.

Fumes and Gases can be hazardous to your health

- Before use, read and understand the Material Safety Data Sheet (MSDS), the manufacturer's instructions, and your employer's safety practices.
- If MSDS is not enclosed. Obtain from your employer.
- Keep your head out of the fumes. See Section 5 of the MSDS for specific fume concentration limits.
- Use enough Ventilation, exhaust at the arc, or both, to keep fumes and gases from your breathing zone and the general area. If needed, use a proper respirator.
- No hazards exist before this product is used in arc welding.

Electric Shock can kill

- Always wear dry insulating gloves
- Insulate yourself from work and ground.
- Do not touch live electrical parts.

ARC Rays can injure eyes and burn skin

- Wear welding helmet with correct filter.
- Wear correct eye, ear, and body protection.

Welding can cause fire or explosion

- Do not weld near flammable material.
- Watch for fire, keep, extinguisher nearby.

Read American National Standards Z49.1, "Safety In Welding, Cutting and Allied Process," from American Welding Society.