

Stainless Steel Electrodes (MMAW)

SME 308L-16



 **SENOR[®]**
One Stop Solution for Welding & Brazing Consumables

SME 308L-16

Stick Electrodes (MMAW)

Stainless Steel

Classifications:

AWS A/SFA 5.4 : E 308L-16
 IS 5206 : E 19.9 LR26
 Coating Type : Rutile
 Coating Factor : Medium
 Identification : Brand Printed

Characteristics:

In SME 308L-16, the weld deposit contains a maximum of .04% carbon, which minimizes the formation of chromium carbides, and consequent susceptibility to intergranular corrosion, The weld deposit, with controlled ferrite, gives excellent notch toughness. The slag is easily controlled and does not interfere with the arc action. Weld beads are smooth, and of good appearance.



Applications:

- 1) Welding of 18Cr/8Ni grade Stainless Steels such as AISI types 301, 302, 304 and 308 having low Carbon content.
- 2) Shipbuilding
- 3) General Fabrication
- 4) Tubes, tanks, heat exchangers, piping systems

Mechanical Properties – All-Weld:

Condition	UTS MPa	% Elong (L=4Xd)	RA %	Ferrite No.
As Welded	530-650	35-40	50 min.	3-7

Weld Metal Chemistry (wt%):

C	Mn	Si	S	P	Ni	Cr
0.04 max	0.60-2.0	0.30-0.85	0.03 max	0.04 max	9.0-11.0	18.0-21.0

Current Conditions: AC, DC (+):

5.0	4.0	3.2	2.5	2.0	1.6
150-180	110-140	80-100	50-75	35-45	25-35

Welding Positions:

F, H, V-up, OH

Re-drying Conditions:

To obtain best results re dry the electrodes at 300°C for 1hour (Optionally available in vacuum-packed condition, re-drying not required in this packaging).

Note On Usage:

- 1) Keep electrode dry (Optionally also available in vacuum-packed condition, redrying not required in this packaging)
- 2) To obtain best results rebake the electrodes at 250 ~ 300°C for 1 hour and keep it at 100 ~ 150°C prior to use.
- 3) Use stainless steel wire brush for cleaning of slags
- 4) Follow the recommended welding parameters to achieve good sound welds
- 5) Do not use excessive currents. Hold short arc. Use good fit-up on joints.

Above are basic guidelines and will vary depending on joint design, number of passes and other factors.

⚠WARNING Ⓢ

Protect yourself and others. Read and understand this warning. Do not remove this warning.

Fumes and Gases can be hazardous to your health

- Before use, read and understand the Material Safety Data Sheet (MSDS), the manufacturer's instructions, and your employer's safety practices.
- If MSDS is not enclosed. Obtain from your employer.
- Keep your head out of the fumes. See Section 5 of the MSDS for specific fume concentration limits.
- Use enough Ventilation, exhaust at the arc, or both, to keep fumes and gases from your breathing zone and the general area. If needed, use a proper respirator.
- No hazards exist before this product is used in arc welding.

Electric Shock can kill

- Always wear dry insulating gloves
- Insulate yourself from work and ground.
- Do not touch live electrical parts.

ARC Rays can injure eyes and burn skin

- Wear welding helmet with correct filter.
- Wear correct eye, ear, and body protection.

Welding can cause fire or explosion

- Do not weld near flammable material.
- Watch for fire, keep, extinguisher nearby.

Read American National Standards Z49.1, "Safety In Welding, Cutting and Allied Process," from American Welding Society.